

Bulletin nr.	ALG14001ENG
Date	31-01-2014
Subject	LDT update V15.0
Brand / Type	LPi, LPfi, LPdi

New software in LDT:

With update version V15.0 there have been a number of updated software's and new released.

New LPi / LPfi Master-file:

SOFTWARE MASTER 920v8 tbv LPi / LPfi	206920.8
--------------------------------------	----------

- Maximum system pressure increased from 27 to 30bar
- Dishonest error P0203 solved
- Several small bugs concerning AFS (Automatic Fuel Switch) solved

New LPdi Master-file:

SOFTWARE MASTER 961v2 tbv LPdi (FSU3)	206961.2
---------------------------------------	----------

- Possibility for an extra LPG-injector, introduced with the EcoBoost engines.
- AFS resetlevel lowered to > 0,45V
- Several small bugs solved

Additional new calibration-files:

Skoda Rapid 1.2 Tsi 63kW CBZA / ECT1 / LPdi	2028003.7
Skoda Rapid 1.2 Tsi 63kW CBZA / ECT2 / LPdi	2028013.3
Ford Focus III 1.6 SCTi Ecoboost 134kW JTDB (FSU3) / LPdi	2028020.0
Toyota Prius Plus 1.8i Hybrid 73kW 2ZR-FXE	2021347.1

Additional electrical diagram Ford 1.6 EcoBoost engines